



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com

Quality Management
System Certificate
UNI EN ISO 9001:2015

Name: POLYTECH TROUSERS	Code: MC5711Q5	MC57 CLOTHING - POLYTECH SERIES
--------------------------------	-----------------------	--

Description

Trousers made of a technical fabric composed by 75% cotton, 24% polyester, 1% antistatic fibre, weight 280 g/m . It features a fly with zip and button, two front pockets with flap and Velcro, rear pocket with flap and Velcro, two three-dimensional functional pockets with flaps and Velcro.



THE TROUSERS SHALL BE WORN IN COMBINATION WITH THE JACKET.

- The Polytech series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products.
- Thanks to its features it is multi-purpose, practical and resistant, breathable and comfortable.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425.

In combination with the coverall, is it possible to wear our under garments: Carboflame undershirt art. MC5610 and Carboflame underpants art. MC5620.

certified



Category III	Colours DARK BLUE	Available Sizes 38 - 70
------------------------	-----------------------------	-----------------------------------

Quantity/Carton 50	<p>EC Standards</p> <p>EN 1149-5 </p> <p>EN ISO 11611 Class:1 Values:A1</p> <p>EN ISO 11612 Limited Flame Spread:A1 Convective Heat:B1 Radiant Heat:C1 Molten Iron Splashes:E3 Contact Heat:F1</p> <p>EN 13034 Type:6</p> <p>IEC 61482-2 APC:1</p>	<p>Important Information</p> <p>Petrochemical Industry, Metalworking Industry, Refining Industry, Chemical Industry, Industrial Maintenance and Assemblies, Gas, Water and Electricity Mains Maintenance and Management, Oil & Gas industry.</p> <p>Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.</p> <p>We recommend to follow the washing instructions. Wash separately from other types of garments to avoid the transfer of inflammable fibres.</p>
	Dexterity	