



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com

Quality Management
System Certificate
UNI EN ISO 9001:2015

Name: POLYTECH JACKET	Code: MC5714Q5	MC57 CLOTHING - POLYTECH SERIES
------------------------------	-----------------------	--

Description

Jacket in 75% cotton, 24% polyester, 1% antistatic fibre fabric, weight 280 g/m . It features a Chinese collar with Velcro for neckprotection, concealed front zipper closure with metal snap buttons, two lower pockets and two chest pockets with flaps and Velcro, elastic cuffs, military style epaulettes on shoulders, reflective piping on the chest.

THE JACKET SHALL BE WORN IN COMBINATION WITH THE BIB-TROUSERS OR TROUSERS.

- The Polytech series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products.
- Thanks to its features it is multi-purpose, practical and resistant, breathable and comfortable.

The product is designed and manufactured to comply with the requirements of Regulation (EU) 2016/425 and subsequent amendments.

In combination with the jacket is it possible to wear our under garments: Carboflame undershirt art. MC5610 and Carboflame underpants art. MC5620, meeting the point A.2 of IEC 61482-2 which is stating that the electric arc protective clothing shall be used with under garments made of materials that would not melt with the arc.



Category III	Colours DARK BLUE	Available Sizes 38 - 70
------------------------	-----------------------------	-----------------------------------

Quantity/Carton 20	EC Standards	<p>Important Information</p> <p>Petrochemical Industry, Metalworking Industry, Refining Industry, Chemical Industry, Industrial Maintenance and Assemblies, Gas, Water and Electricity Mains Maintenance and Management, Oil & Gas industry.</p> <p>Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.</p> <p>We recommend to follow the washing instructions. Wash separately from other types of garments to avoid the transfer of inflammable fibres.</p>
Dexterity		